



KAPCI
COATINGS



Technical Data Sheet	
Issue: January 2021	for professional use only

Kapci K80 Wax Polish

Product description

Kapci K80 is a wax Polish used to delivers a high gloss finish after applying compound Kapci K10, K15 compound. Or Latico 5000

Product Placement in Kapci Polishing System

Fast Cut	Medium Cut	Fine cut	Protection
Kapci K10	Kapci K40	Kapci K60	Kapci K90
Kapci K20			Kapci 80
Kapci K15			Latico 5050
Latico 5000			

Physical, Chemical and General information

Product group	Contains Silicone and wax
Viscosity	22-35 pois
Density	0.95-1kg/L
Shape	Liquid form
Color	Yellow
Package	0.9L

Technical Information and direction of use

Technical Information	
Cut	N/A
Gloss	10

Direction of use

IMPORTANT NOTE: These TDS are for information purposes only without any obligation as we do not have control over the quality and conditions of the surface or application.



KAPCI
COATINGS

Apply wax in a thin layer and keep going in circular motion. Overlap to spread the wax across evenly.

let it sit for a few minutes. To check whether the wax is ready to come off, swipe your finger on the surface. "If the wax smears it is not yet ready, if it is dry and clears away then it is ready."



Wipe off using microfiber cloth, Turn the cloth frequently.

While wiping if you notice that the cloth will start developing more drag through your hand motion. This indicates that you must flip it for a cleaner side and continue.

General notes

- ✓ Apply Kapci K80 out of the direct sunlight.
- ✓ Apply Kapci K80 onto the cool surface.
- ✓ Apply Kapci K80 onto Clean surface.
- ✓

Storage



Keep away from frost.
Store between 15°C and 35°C.
Store in well ventilated area.

Health and Safety

1. For full Health and Safety information refer to the Material Safety Data Sheet (MSDS).
2. Observe the precautionary notices displayed on the container.
3. Goggles and gloves should be worn while using these products.
4. Good ventilation must be provided in the working environment.

IMPORTANT NOTE: These TDS are for information purposes only without any obligation as we do not have control over the quality and conditions of the surface or application.